
HISTORIC AMERICAN BUILDINGS SURVEY



HABS No. MD-307-D

INDEX TO PHOTOGRAPHS

Fort Washington, Fort Fort Washington Road Fort Washington Forest vicinity Prince Georges County Maryland

Abbie Rowe, Photographer, July 27, 1957

MD-307-D-1

PERSPECTIVE VIEW (NORTHEAST) FROM ESPLANADE OF NORTHWEST DEMI-BASTION SHOWING GLACIS AND RELATIONSHIP TO MAIN GATE

Abbie Rowe, Photographer, April 11, 1957

MD-307-D-2

PERSPECTIVE VIEW (NORTH) INTO ESPLANADE OF NORTHWEST DEMI-BASTION SHOWING REVETMENTS, COUNTERFORTS, GLACIS AND STAIRS

MD-307-D-3

PERSPECTIVE VIEW (SOUTH) INTO ESPLANADE OF NORTHWEST DEMI-BASTION SHOWING REVETMENTS, COUNTERFORTS, GLACIS AND STAIRS

Abbie Rowe, Photographer, June 21, 1957

MD-307-D-4

DETAILED ELEVATION (SOUTH) OF LOWER STAIR STRUCTURE

Abbie Rowe, Photographer, June 7, 1957

MD-307-D-5

DETAILED VIEW OF DOOR HINGE ON REVETMENT OF NORTHWEST DEMI-BASTION

Abbie Rowe, Photographer, March 12, 1958

MD-307-D-6

DETAILED VIEW OF DOOR ON REVETMENT AFTER RESTORATION

Abbie Rowe, Photographer, August 14, 1957

MD-307-D-7

PERSPECTIVE VIEW (EAST) OF NORTH TERREPLEIN OF NORTHWEST DEMI-BASTION SHOWING GUN MOUNTS AND RELATIONSHIP TO MAIN GATE

Abbie Rowe, Photographer, June 19, 1958

MD-307-D-8 PERSPECTIVE VIEW (WEST) OF NORTH TERREPLEIN OF NORTHWEST DEMI-BASTION SHOWING GUN MOUNTS

Abbie Rowe, Photographer, August 14, 1957

MD-307-D-9 PERSPECTIVE VIEW (NORTH) OF WEST TERREPLEIN OF NORTHWEST DEMI-BASTION SHOWING GUN MOUNTS

Abbie Rowe, Photographer, October 2, 1958

MD-307-D-10 PERSPECTIVE VIEW (SOUTH) OF WEST TERREPLEIN OF NORTHWEST DEMI-BASTION SHOWING GUN MOUNTS AND RELATIONSHIP TO ESPLANADE AND BARRACKS

Abbie Rowe, Photographer, December 19, 1957

MD-307-D-11 DETAILED VIEW (NORTHWEST) OF SLOPED SOUTH PARAPET CAP SHOWING REINFORCING TIES

Abbie Rowe, Photographer, August 14, 1957

MD-307-D-12 DETAILED VIEW OF EMBRASURES ON WEST EXTERIOR WALL OF NORTHWEST DEMI-BASTION

Abbie Rowe, Photographer, April 11, 1957

MD-307-D-13 DETAILED VIEW OF SALLY PORT GATE ON WEST CURTAIN WALL

Abbie Rowe, Photographer, March 12, 1958

MD-307-D-14 PERSPECTIVE VIEW (NORTH) INTO ESPLANADE OF SOUTHWEST DEMI-BASTION SHOWING REVETMENTS, RESTORED DOORS, GLACIS AND STAIRS

Abbie Rowe, Photographer, July 19, 1957

MD-307-D-15 PERSPECTIVE VIEW (NORTHWEST) OF WEST RETAINING WALL IN SOUTHWEST DEMI-BASTION SHOWING GLACIS

HISTORIC AMERICAN BUILDINGS SURVEY Index to photographs
Fort Washington, Fort

HABS No. MD-307-D (Page 3)

Abbie Rowe, Photographer, October 4, 1957

MD-307-D-16

PERSPECTIVE VIEW (NORTHEAST) OF WEST TERREPLEIN OF SOUTHWEST DEMI-BASTION SHOWING RELATIONSHIP TO MAIN GATE AND OFFICERS' QUARTERS

Abbie Rowe, Photographer, August 28, 1957

MD-307-D-17

PERSPECTIVE VIEW (WEST) OF SOUTH EXTERIOR WALL OF SOUTHWEST DEMI-BASTION